

## **SAS Superstructure**

Location: 04-SF-80-13.2 / 13.9 Client Name: CalTrans

Daily Diary Report by Bid Item

Contract No.: 04-0120F4

Diary #: 012 Const Calendar Day: 156 Date: 11-Feb-2010 Thursday
Inspector Name: Mathur, Lalit Title: Transportation Engineer

Inspection Type: Intermittent

Shift Hours: 07:00 am 05:15 pm Break: Over Time: 02:00

Federal ID: Location:

Reviewer: Klebanov, Gilel Approved Date: 07-Apr-10 Status: Approved

Weather

**Temperature 7 AM** 50 - 60 **12 PM** 50 - 60 **4PM** 50 - 60

Precipitation 0 Condition

Working Day 🗸 If no, explain:

04-0120F4 Bid Item: 056 E-L01-OBG.056 E Line Lift 01 OBG Erect structural steel

AMERICAN BRIDGE/FLUOR, A JV

04-0120F4 Bid Item: 056 E-L02-OBG.056 E Line Lift 02 OBG Erect structural steel

AMERICAN BRIDGE/FLUOR, A JV

Diary:

General Comments 056 E-L02-OBG.056

Pier 7 Activities

.

- ·ABF was using Pier-7 Gantry crane, Boom crane, barge crane, forklifts and man lift.
- ·ABF finished unloading the temporary work items from the Ship HUA 18.
- •The ship sailed out at about 8:45 AM. (about 15 minutes late)
- ·ABF continues to work Lift 3-E. There was only Lift 3-E on this barge.
- ·Later ABF brought the barge with Lift 1-W and 4-W and started working on these as well.
- I checked the operations in the morning, noontime and later in the afternoon.

**OBG Lift Activities at Site:** 

- ·ABF people started working at 7:00 AM.
- •There was a safety meeting by ABF. There were 11 workers with blue hats and 12 others with white hats including 6-8 from Caltrans.
- ·Gil, Lalit, Masoud, Philip, Tai, Jason, Bob, Thanh were all there in the morning
- •The ABF safety meeting was followed by a demonstration of apply torque on the bolts.
- ·Lift 2-E operations.

oABF worked all morning to prepare for moving the Lift 2-E to Lift 1-E.

oMasoud and Philip watched this operation.

oBy 11:30 AM, ABF was ready to install the top bolts of the seismic stops.

oDavid observed the operation with Lalit.

oBy 4 PM they were done with installation of the top bolts. Many of the bolts were observed spinning after being snug tight during the pre-tensioning.

oBottom bolts were not installed.

oABF then started to slide Lift 2-E to close the 1.5 meter gap.



Page 1 of 2

Run date 21-Nov-14

6:19 PM

Time

04-0120F4

04-SF-80-13.2/13.9

Self-Anchored

Suspension Bridge

## Daily Diary Report by Bid Item

Job Name: 04-0120F4 Inspector Name Mathur, Lalit Diary #: 012 Date: 11-Feb-2010 Thursday

oABF installed the 4-longitudinal jacks for each Lift.

oABF put Lift 1-E on jacks.

§The actual sliding operation started at 1:45 PM and by 2:30 PM, the Lift 2-E was 50 mm away from Lift 1-F

§The sliding operation was stopped.

§ABF started to prepare for gap closing operation.

§A team of welders was brought in at about 3:30 PM.

§ABF started to prepare a back bar long enough to cover the width of OBGs.

§Jason's group covered the welding operation.

·Lift 1-E operations

oABF put the Lift 1-E on jacks. Like Lift 2-E, ABF installed the Longitudinal Jacks with 1 1/8" diameter rods.

oABF performed the same tasks here to pull the Lift 2-E to within 50 mm.

oABF lifted Lift 1-E on the jacks again.

ol noted the jack pressure.

oThese were as follows:

§NW 3000 psi, NE 3250 psi, SW 5500 psi and SE 1000 psi

·Shear Leg Crane and Lifting Frame additional Operations

oShear Leg crane did not work.

## Other Activities:

- ·Attended Safety Meeting at 8 AM followed by Gary Pursell's staff Meeting.
- ·There was discussion about access issues.
- •There was discussion about ABF's employees attitude and behavior with CT people.
- •There was discussion about the quality of work performed by ABF.
- •There was discussion that we do not even know what did they change in CT's absence.

Reviewed revised forms for 2-E as suggested by Tai-Lin and ABF.

Lalit, David, Philip and Masoud worked late.

Charged 2 hours OT.